VIA E-MAIL - Redacted

Redacted

Dear Redacted

Request for Records Re:

Freedom of Information and Protection of Privacy Act

The City of White Rock has reviewed your request for access to the following records pursuant to the Freedom of Information and Protection of Privacy Act (the "Act"):

- a copy of the following documents concerning 1497 Martin Street from August 14, 2011 to date:
 - Approved (stamped) building permit drawings from Scott Gordon Architect for the building permit #11-152 issued on or about April 4, 2012 (the "Building Permit");
 - 2. Any engineering reports forming part of the Building Permit;
 - 3. All email correspondence between the City of White Rock and Scott Gordon of Scott Gordon Architect: and
 - 4. All documentation regarding flooring at the Property, if applicable;
 - All drawings, design reports, inspection reports from Scott Gordon Architect;
 - 6. All drawings, design reports, inspection reports from structural engineer for the Building Permit;
 - 7. All drawings, design reports, inspection reports from mechanical engineer for the Building Permit;
 - 8. All drawings, design reports, inspection reports from electrical engineer (SML Consultants Group Ltd.); and
 - 9. All inspection reports and documents from the City of White Rock.

We have been able to locate some responsive records to your request. Access to these records is available, however some of the information in the records is excepted from the disclosure requirements of the Act. I have severed the excepted information so that I could disclose to you the remaining information as attached.

Corporate Administration

P: 604.541.2212 | F: 604.541.9348

City of White Rock

15322 Buena Vista Avenue, White Rock BC, Canada V4B 1Y6



The severed information is excepted from disclosure under section 22 of the Act. Severing is necessary to avoid disclosing any third-party personal information without permission.

Please contact our office if you have any questions or concerns.

Sincerely,

Ken Overton

 ${\bf Manager,\, Property,\, Risk\, Management,\, and\, FOI}$

604-541-2104

Att.

If you believe that the City of White Rock has been unreasonable in its handling of your request, you may ask the Information and Privacy Commissioner to review our response. You have 30 days from receipt of this notice to request a review by writing to:

Office of the Information and Privacy Commissioner 3rd Floor, 756 Fort Street Victoria BC V8W 1H2

Should you decide to request a review, please provide the Commissioner's office with:

- 1. your name, address and telephone number;
- 2. a copy of this letter;
- 3. a copy of your original request sent to the City of White Rock; and
- 4. the reasons or grounds upon which you are requesting the review.



PLANNING AND DEVELOPMENT SERVICES 15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

White Rock, B.C. Tel: 604-541-2136 Fax: 604-541-2153

City Hall,

Inspection Report

Redacted 5. ZZ	PERMIT No.:
ADDRESS: 1497 MARTIN	SHEET No:
TYPE OF INSPECTION: FINAL	DATE: SEP 14/16
AREA OF INSPECTION:	
A lind Oh	
1,1,1,0	
REN'D	\
VC-A-1C-B	Lago From Aux.
(Ch	
time on	
	20 12 0 14 1
	· · · · · · · · · · · · · · · · · · ·
	w w
	· · · · · · · · · · · · · · · · · · ·
SIGNATURE:	INSPECTOR: Primer DYHII
DATE:	



PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

City Hall, White Rock, B.C. Tel: 604-541-2136 Fax: 604-541-2153

Inspection Report

NAME: White Stane Mano	PERMIT No.: 15059
ADDRESS: 1497 Martin 5	SHEET No:
TYPE OF INSPECTION: Q/mbine	9 DATE: AM9 21/13
AREA OF INSPECTION: Unit 10	11.
@/4mbing	tinal unit 101
- 0 5 6 LOV	ed.
	in the second se
- A	the state of the s
$C \sim A + C \sim D$	Kag D From Huld:
	
-	
	1.11
	+40N
SIGNATURE:	INSPECTOR:
DATE:	/

Please sign this form when the work is completed and return to the above department.



PLANNING AND DEVELOPMENT SERVICES 15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Inspection Report

City Hall, White Rock, B.C. Tel: 604-541-2136 Fax: 604-541-2153

Redacted S. 22	PERMIT No.: 13.039
ADDRESS: 1497 Martin	SHEET NO:
ADDRESS: 1497 Martin TYPE OF INSPECTION: Dumbins	DATE: May 17/13
AREA OF INSPECTION:	
DWV + Water	lai <
- WAAI	m ų s
Amorand	
111.	
	· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·
	XX
SIGNATURE:	INSPECTOR:
DATE:	
Please sign this form when the work is completed a	ind return to the above department.

1497 Martin St., White Rock, B.C. - FIRE RESTORATION

max 6 m long dead end corrid

Redacted

1 Ground Floor Plan
Scale: 3/32* = 1'-0'

GENERAL NOTES

Exhaing entry door 20 min /PS trame over self door

All wallshirsther existing

Expanded Plan
Scale 3/32* • 1-0*

Bulkhead Detail

SCOTT GORDON ARCHITECT

MAIBC AIA

3370 West 44th Avenue Vancouver, B.C. VeN 3X8

Tel. (604) 203-0410 Fax (604) 263-4106

NORTH

pypingsmed distribution of an engine of distribution between a glassification and section is a classification and section is


1497 Martin St. White Rock, B.C. Fire Restoration

The Juny

(Import has no

HEX 161 TUM, Mar 5, 2013

1497 Menth Sil, White Rock, B.C., : IFIRE HRESTORATION




Ground Floor Plan


GENERAL NOTES

· All wallshirtshee existing

· Existing entry door 20 min IPS frame cas self door



Expanded Plan



SCOTT GORDON ARCHITECT

The state of the s

MAIBC AIA

3370 West 44th Avenue Vancouver, B.C. V6N 3K8

Tel. (604) 263-0410 Fax (604) 263-4106

€.60A. 120.8272

NORTH

Cay angle figure on a special recurs. This pro- on progress, diet of the transfers, for basicative, progress of Sich contact Authorities, and common to

1497 Martin St. White Rock, B.C. Fire Restoration

tills dispers

BEHARLIMA A

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitoring Report

1497 Mortin St. Property Address:_ Coordinating Registered Professional: Scott Gordon Owner/Contractor: Belfor Restoration. Stage of Work: _____ schedules received Building Official:

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.



THE RESERVE AND ASSESSED ASSESSED AND ASSESSED ASSESSED.

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitoring Report

Property Address: Coordinating Registered Professional:_ Owner / Contractor: _____ Stage of Work: __ Building Official:

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitoring Report Date: A49 31, 2012
Property Address: 1497 Martin St
Coordinating Registered Professional: Scott Gerdan
Owner/Contractor: Belfor Restaration.
Stage of Work: Ing/ tire damage.
i) fire department key tube (10ch.
z) fire safety plan change regid still
3. / unt 100 (office) regair all holes
ogenings in fire segarations. (03 discussed) chywall bathroom-
openings in fire seconstians. (os discussed) chywall bathroom - and fire toge - chywall all ceiling genetrations including ceiling fan -
4) all schedules & documentation regil

5.) regain genetration holes in ceiling of mech wom.

Building Official:

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.



Please refer to our website (<u>www.safetyauthority.ca</u>), or contact a BCSA Regional office nearest you:

Coguitlam 604-927-2041 fax 604-927-2047 Kamloops 250-314-60

Coquitlam 604-927-2041 Kelowna 250-861-7313 Nanaimo 250-716-5200 Victoria 250-952-4444

fax 250-861-7349 fax 250-716-5212 fax 250-952-4458 Kamloops Langley Prince George 250-314-6000 604-539-3573 250-614-9972 fax 250-377-4406 fax 604-539-3570 fax 250-614-9949

New Westminater 505 Sixth Street, Suite 200, New Westminster, BC V3L 0E1 Toll free: 1-866-566-7233 Fax 1-888-660-3508

ELEVATING DEVICES CERTIFICATE OF INSPECTION

Note: The information on this form is collected to administer the provisions of the BC Safety Standards Act. If you have questions about the collection, use, or disclosure of this information, contact the Records, Information and Privacy Analyst for the BC Safety Authority at 1-866-566-7233.

If you disagree with this Certificate of Inspection you may request, in writing, a Safety Manager review within 30 days of receipt of this Certificate. You can obtain the Review Request Form from any Safety Authority office or online at http://www.safetyauthority.ca/enforcement/enforcement-process.

A. Inspection		-								
Activity YYY			Unit n		Status:		emp Perm	Dis	S/D	Const.
date: 201				2773 Unit Name:	,, 1	_0_	2 3	4	5	6
	WHITE STO		-	Area:	#1	Class:	PE	Type	00	
1447		ST Postal Code:		Contact:	50	I Cidoo	Phone:	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	BSMT	73
(2) Owner/Agent nar		7. 6.3. 6. 6. 6.00.6.		Oor lade.			Licence no.:			
	# 010		70	(3) Contract	tor nome:		1			-
# 201	15272	CROYDON ST	7		tor name:	WES?	COAST			
City: WHITE	ROCK/SURREY	Postal Code:		Invoice:		1	2		(3)
Manufacturer/Suppli	er:	Contract no./Model	no:	Capac	ity: LBS.:	500	KGS:		Floors:	3
Operating	ra.a.	Building used as:			test: date te		Where an ir			
FPM:	M/S:	APARTM	ENT	YYY	Ү ММ	DD	any persons equipment, in 24 hours			
B. Non-Compl	iances may re	sult in shut dow All non-compliance				necified			Code	
item	SPECIAL	INSPECTION	7		CHEC)		Code	
-		PERATOR. L	laur Con			KIN	,			
	SERVICE		AVIT CAR	OF TO	1 OAC	N IN				
	25010			-				-		
		\								
										_
- 3										
		k					-			
				/	-				9	
				1			-			
No. 200	L	and the second				•	70. V. C. C. C. C. C.		1 '- 20 1	
Non-Compliances		completed within:					nust be comple	eted wi	thin 90 da	ays
		ng when non-compliar								2001
This device is shut of	down until direction	is:	have been o	ompleted and	permission t	or return to s	ervice has bee	n grant	ed by the	BCSA
C. Declaration						,				
							operating perm			
operating permit or		elevating device with construction use	out a valid	T-		·	construction us		_	
Client Signature:	-2			Acceptance Safety Office		Partial			omplete y Officer i	no .
× 10	~LSOU	CUS		Juliony Office	J. Digitatore	1/ 1/4	Line	-with	48	
`~tivity type			C/H Ext. One	Hour Docum	ent No.:	1 level	No. of p	ages:	.0	
-	Reg. Acc.	(3) 4		В	1644	180		-		
Accommodation	Km	Cost	Me	als	Ferry/A		Billable Hours	1	Mis	ic.
		777								
						-				

White - Owner's Copy

Yellow - File Copy

Blue - Safety Officer's Copy

PRINTED NON-COMPLIANCES

All non-compliances shall be completed within the time limits specified

General / Elevators

- 1- Install correct rated fuses in the disconnect switch.
- 2- Install correct rated fuses in the controller.
- 3- Mark the equipment in the machine room so that the main components for each installation may be identified.
- 4- Install or repair a lock on the machine room door.
- 5- A key to the elevator machine room shall be kept available and accessible to authorized persons at all time.
- 6- Remove all material from machine room not related to the elevator.
- 7- Obtain from this branch and install a replacement metal installation number plate.
- 8- The alarm bell shall ring when the emergency stop switch is actuated.
- 9- The car emergency light unit shall be tested by qualified persons and repaired if necessary.
- 10- Car enclosure and suspended ceiling material flame spread rating shall conform to code requirements.
- 11- Adjust the car gate or door contact to prevent the operation of the car until the door or gate is in the closed position.
- 12- Adjust the door closing mechanism so that the force exerted by the door edge does not exceed 30 pounds (13.5 kg).
- Adjust or replace self closers on landing doors to fully close the doors from all positions.
- 14- Adjust the hoistway door eccentrics.
- 15- Check and secure landing gate posts and guides.
- 16- Replace missing or worn landing door gibs.
- 17- Install approved landing door hanger rollers or install metal door retainer brackets.
- 18- Clean the hoistway, rails, top of car and other equipment.
- 19- Remove the debris from the elevator pit.
- 20- Remove the water from the pit and provide means to keep the pit dry.
- 21- The elevator safety device shall be examined & tested by qualified person and a declaration shall be submitted to the BCSA.
- 22- Equalize the tension on the hosting ropes.
- 23- Replace the hoisting ropes.
- 24- Replace the governor rope.
- 25- Shorten the hoisting ropes to provide sufficient runby for the car to engage the upper final limit.
- 26- Maintain a minimum of one full turn of rope on the drum when the car has reached its extreme limit of travel.
- 27- Remove oil from the pit and check the gland packing.
- 28- Identify and tag the manual lowering valve.
- 29- Set the relief valve to open at not more than 125% of the operating pressure.
- 30- Replace the flexible hose oil line.
- 43- The elevator car doors shall not open automatically outside of the leveling zones.
- 44- All emergency signal devices shall operate under emergency power.
- 45- An auxiliary contactor shall be provided with contacts in series with the direction contactor(s).
- 46- Re-install all controller covers.
- 47- Secure all loose sight guards.
- 48- The top of car/pit lighting shall be made operational.
- 49- All rags shall be kept in a closed metal container in the machine room.
- 50- The main disconnect switch fuses/overloads shall be sized to the motor data plate.
- 51- The machine room door shall be self-closing and self-locking
- 52- Remove all pipe-work from machine room not required by applicable codes and by-laws.
- 53- Minimum hydraulic oil level indication shall be provided.

- 54- The driving-machine brakes shall be examined, maintained, inspected & tested by qualified person and a declaration shall be submitted to the BCSA.
- 55- The governor device shall be examined, maintained, inspected & tested by qualified persons and a declaration shall be submitted to the RCSA
- 56- The pull-through force of the governor shall be tested by qualified persons and a declaration shall be submitted to the BCSA.
- 57- The governor tripping speed shall be tested by qualified persons and a declaration shall be submitted to the BCSA.
- 58- Inspections and tests for Ascending Car Over-speed, and Unintended Car Motion Protection shall be tested by qualified persons and a declaration shall be submitted to the BCSA.
- 59- The oil buffers shall be examined, maintained, inspected & tested by qualified person and a declaration shall be submitted to the BCSA.
- 60- The hydraulic cylinder shall be examined, maintained, inspected & tested by qualified person.
- 61- Car communication must be connected and operational.
- 62- Emergency Power, Fire Service and/or Seismic operation must be tested.
- 63- Provide tag(s) on ropes and/or governor rope.
- 64- Ventilation/Heating must be connected and operational.
- 65- Provide crosshead data plate.
- 66- Update/complete records in the log book.

Escalators / Moving-walk

- 31- Adjust the machine brake to provide a safe stop.
- 32- Reduce the running clearance on either side of steps to 3/16" (5mm) and the sum of clearance on both sides shall not be more than 1/4" (7mm)
- 33- Reduce the clearance between the steps on horizontal run to a maximum of 5/32" (4mm).
- 34- Reinforce the skirt panels to limit their deflection to 1/16" (5mm).
- 35- Apply friction reducing material to the step risers and skirt panels.
- 36- Replace or install an approved soffit guard at the intersecting ceiling and deck, with red leading edge.
- 37- Provide and affix a sign reading "Emergency Stop" with 1/2" (12mm) or higher red letters on a white background with an arrow indicating the location of the emergency stop button.
- 38- Provide and affix clearly visible signs at the top and bottom reading "Please hold handrail".
- 39- Eliminate the pinching hazard between handrail and decking.
- 0- Replace the damaged step treads.
- 41- Replace the broken or worn combplates.
- 42- An interior examination, inspection and test of all safety devices shall be conducted by qualified person and a declaration shall be submitted to BCSA.

Construction Hoist

- 80- Guarding/hoarding on landings and landing platforms must be as per code requirements.
- 81- The distance from the face of the car door to the face of the hoistway door shall not exceed 200 mm (8 in).
- 82- Adjust sill to sill clearance.
- 83- Provide "DO NOT REMOVE" sign on shoring.
- 84- Landings and landing platforms shall be illuminated when a hoist is in
- 85- Provide slipping protection on ramps.
- 86- Provide numbering on gates.
- 99- Additional non-compliances.



PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitoring Report

Date: Aug 2, 2012
Permit #: 11/52. Property Address: __ Coordinating Registered Professional: ___ Owner / Contractor: _____ Stage of Work: _____ Building Official:

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.



Certificate of Verification

CAN/ULC-S537-04

No. 270712HL

THIS CERTIFIES that the Mircom Fire alarm equipment

Installed by: WESPAC ELECTRICAL CONT.

Located at:

WHITE STONE MANOR 1497 Martin Street White Rock, B.C.

This certificate must be revalidated By July^{26th}, 2013 as per ULCS536

Was checked and inspected by a trained technician. Issued in Maple Ridge on the 27th day of July, 2012

MIRCOM TECHNOLOGIES LTD.

Technician's Signature Hong Liang

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitoring Report Property Address: Coordinating Registered Professional: Owner / Contractor: Kina, Stage of Work: _ were replaced Building Official:

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monito	ring F	Report	Date:	y Eq, 2012
		Yartin St Scott C		
Coordinating Registero	ed Professional:_ 5e/f	Scott C	pordan.	
Stage of Work:	site	review.		
<i>Y</i>	note.	fire fight	nter ladder	required
	-		- to-	
		Ч		
			•	
	A Mention of the Control of the Cont			
			-	
	1.			
suilding Official:	Flor		-	

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.



f	ie	ld	re	p	0	rt

Project: 1497 MARTIN STREET	Report No.: 5		
Owner:	Date: May 21 12		
Contractor: BELFOR	Temperature:		
In Attendance: SGA	Weather:		


Site visit to review installation of thermal and acoustic batt insulation.

Work is good quality and acceptable to install gypsum board.

regards

scott

scott





field report

Project: 1497 MARTIN STREET Owner: Contractor: BELFOR In Attendance:	Report No.: 4 Date: May 15 12 Temperature: Weather:
Richard Wilson,	
Good afternoon- am sending you this as an update as	to progress on site:
1] firestopping as been reviewed and signed off.	
2] the garbage shaft is being decommissioned by bloc sprinkler head, so in effect it becomes a rated shaft in	-
3] the fire alrm system is near ready to install and elec-	trical inspections have been ongoing.
4] the door supplier has located a rated peep hole that contractor has chosen to order this feature with the do	
٠.	
regards	•
scott	.^.
Scott Gordon Architect per:	Distribution X Architect X Field X Owner X Contractor

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitoring Report	
operty Address: 1497 Martin	<i>5</i> † `
ordinating Registered Professional: Scott	Gordon
vner / Contractor: Belfore	
age of Work: fire stopping	
sine strin min	thing poplication
approved.	Iking opplication
recall for ins	ulation :
	200
Arch report requ	fired for firestopping.

Aun h

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.

Building Official:

PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Property A Coordinatio	nitoring Report Date: Ass. 5, 2012 Permit #:
1) 2) 3.)	all tub/shower divertors require roted segarations of discussed because of agrhoge shoft decommision of remove sprintiler head to reglace all suite doors with zo min FRR of fromes - all other doors 45 min door of fromes. brick in bottom of garbage short cleatrical woom make good all fire rated penetrations.
⇒uilding Of	ficial:

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.

Richard Wilson

rom:

Richard Wilson

ent:

Tuesday, March 13, 2012 4:11 PM

To:

'Scott Gordon'

Cc: Subject: Aaron Visser; Phil Lemire RE: 1497 Martin Street

Good Afternoon Scott,

The City has discussed your last email and offer the following comments.

- Smoke detectors are required in the hallways not smoke alarms as indicated on the drawings.
- · Heat detectors required in each suite throughout as per FA system upgrade.
- Hard wired Smoke Alarms are required in each suite in the building

Please include the above in the total scope of work which should include all fire related restorations including upgrades and renovations the owner has planned. All plumbing fixtures in 21 suites are being replaced including a substantial amount of water piping, rain water leaders in the building.

Please understand a full scope of work is required and costing so we can finalize issuance of a permit.



Richard Wilson, Reo Chief Building Official

Planning and Development Services Department P:(604) 541-2145 15322 Buena Vista Ave, F:(604) 541-2153 White Rock, B.C. V4B 1Y6 wilson@whiterockcity.ca www.whiterockcity.ca



This email and any attachments are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the named addressed or have received this communication in error, please notify the sender immediately by email, delete this email and any attachments from your system, and do not disseminate, distribute or copy this email and any attachments. Thank you

From: Scott Gordon [mailto:scott@scottgordonarchitect.com]

Sent: Tuesday, March 13, 2012 9:11 AM

To: Richard Wilson Cc: Aaron Visser

Subject: Re: 1497 Martin Street

Good morning- look forward to receiving your direction so we can move forward.

thanks

scott

On 9-Mar-12, at 2:50 PM, Richard Wilson wrote:

Good Afternoon Scott,

I have a meeting with the Fire Chief on Monday to discuss some issues with your last email. Sorry for the delay but he has been away and has just returned. I will get back to you late Monday or Tuesday.

Thanks

Richard Wilson, RBO Chief Building Official

Planning and Development Services Department P:(604) 541-2145 15322 Buena Vista Ave, F:(604) 541-2153 White Rock, B.C. V4B 1Y6 wilson@whiterockcity.ca www.whiterockcity.ca

<image001.jpg>

This email and any attachments are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the named addressee or have received this communication in error, please notify the sender immediately by email, delete this email and any attachments from your system, and do not disseminate, distribute or copy this email and any attachments. Thank you

From: Scott Gordon [mailto:scott@scottgordonarchitect.com]

Sent: Friday, March 09, 2012 9:09 AM

To: Richard Wilson **Cc:** Aaron Visser

Subject: Fwd: 1497 Martin Street

Good morning Richard, further to the email sent to you March 05 could you please send me your approval to the contents of the note so we can request revised pricing from the contractor.

regards scott

Begin forwarded message:

From: Scott Gordon <scott@scottgordonarchitect.com>

Date: March 5, 2012 11:41:19 AM PST (CA)
To: Richard Wilson < rwilson@whiterockcity.ca>

Cc: Aaron Visser <AVisser@specs.ca>, Brent Serediak brent.serediak@scm.ca

Subject: 1497 Martin Street

Richard Wilson Planning and Development Services City of White Rock, BC

Good morning, further to your letter of February 13, 2012 to Scott Williams, we summarize:

- 1. Emergency lighting will be in stairs and common areas only. As shown on the submitted BP Application.
- 2. Garbage room ceiling will be restored to a 3/4 hour rating.
- 3. Mid hallway doors/frames will be removed.



PLANNING AND DEVELOPMENT SERVICES

15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Phone: 604-541-2136 • Fax: 604-541-2153 • www.whiterockcity.ca

Monitor	ing Rep	ort
---------	---------	-----

	s: 1497 Martin St
/ Contract	tor: MVP Plumbing & Heating.
of Work: _	zy units.
1	
	day for domac proing
	day for domage piping replaced & test witnessed
	damaged waterlines test witnessed
	on entire system to diverters. (street pressure up qui):
	(street pressure wasi).
	note. plumbing in bootlegged
d	note plumbing in bootlegged snite to be removed.
M	
100	celling to be exposed for tub trap.
	inspections.

Note: The City of White Rock has relied on the Registered Design Professional for the design, field review and certification in the prescribed Schedules as adopted by the B.C. Building Code for this project, subject to Section 290 of the Local Government Act and City of White Rock Building Bylaw.

Richard Wilson

rom:

Richard Wilson

ent:

Thursday, February 23, 2012 12:33 PM

To:

'Scott Gordon'

Subject:

RE: 1497 Martin Street

Good Afternoon Scott,

Thanks for your comments, see our response in red:

1. In regards to item # 1 of the above noted letter, Under the advisement from our electrical consultant, emergency lighting is not required in laundry, locker rooms, etc. We acknowledge and are willing to accept having to comply with the BCBC that emergency lighting is required in exit stairs and common areas as these areas have been stripped of finishes and are under renovations. I agree - BCBC Appendix A defines what is a service room and it clearly excludes laundry rooms and I would conclude locker rooms also.

2. In regards to item #9 and #14 of the above noted letter:

We propose to run bathroom and kitchen exhausts in fire rated shafts in the fire damaged units only. We refer to BCBC Part 1 Compliance 1.1.1.2 Application to Existing Buildings - the repair of the building....the level of fire safety shall not decrease below the level that already exists. Furthermore in Appendix A Explanatory Material.... it is not the intent of the BCBC to enforce the retrospective application of new requirements to existing buildings.... while the requirements that you outline in item 9 and 14 may have been required at the time of the buildings construction, our work in other Lower Mainland jurisdictions has lead to an understanding hat the cost to the owner of having to correct past wrongs is prohibitive. It is not the intent of the Code to punish but ensure that the building being repaired at completion has an increased level of life safety than before the repair.

The proposed repair work to the damaged suites and common areas and a new Fire Alarm system will ensure an increased level of life safety that was not present prior to the repair work.

Item #14 'charcoal filtered range hood', the BCBC clearly does not permit this. The building originally had code compliant exhausting so the City cannot accept or ignore a lesser standard that has subsequently been installed.

Item #9 'fire rated exhaust shafts' We have reviewed your comments on this issue and accept your reasoning.

Thanks

Richard Wilson, RBO Chief Building Official

Planning and Development Services Department P:(604) 541-2145 15322 Buena Vista Ave, F:(604) 541-2153 White Rock, B.C. V4B 1Y6 wilson@whiterockcity.ca www.whiterockcity.ca

WHITE ROCK
My City by the Seal

his email and any attachments are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the named addressee or have received this communication in error, please notify the sender immediately by email, delete this email and any attachments from your system, and do not disseminate, distribute or copy this email and any attachments. Thank you

From: Scott Gordon [mailto:scott@scottgordonarchitect.com]

Sent: Wednesday, February 22, 2012 4:31 PM

To: Richard Wilson

Cc: Aaron Visser; Brent Serediak **Subject:** 1497 Martin Street

Good afternoon, further to our telephone conversation this morning we would like to outline our position on a number of items in your letter of February 13th, addressed to Scott Williams.

1. In regards to item # 1 of the above noted letter, Under the advisement from our electrical consultant, emergency lighting is not required in laundry, locker rooms, etc. We acknowledge and are willing to accept having to comply with the BCBC that emergency lighting is required in exit stairs and common areas as these areas have been stripped of finishes and are under renovations.

2. In regards to item #9 and #14 of the above noted letter:

We propose to run bathroom and kitchen exhausts in fire rated shafts in the fire damaged units only. We refer to BCBC Part 1 Compliance 1.1.1.2 Application to Existing Buildings - the repair of the building....the level of fire safety shall not decrease below the level that already exists. Furthermore in Appendix A Explanatory Material.... it is not the intent of the BCBC to enforce the retrospective application of new requirements to existing buildings.... while the requirements that you outline in item 9 and 14 may have been required at the time of the buildings construction, our work in other Lower Mainland jurisdictions has lead to an understanding that the cost to the owner of having to correct past wrongs is prohibitive. It is not the intent of the Code to punish but ensure that the building being repaired at completion has an increased level of life safety than before the repair.

The proposed repair work to the damaged suites and common areas and a new Fire Alarm system will ensure an increased level of life safety that was not present prior to the repair work.

regards

scott gordon

February 13, 2012

Scott Williams. 102 - 30701 Simpson Road. Abbotsford, BC V2T 6Y7

Attention:

Scott Williams

Branch Manager

RE: Fire Restoration 20 Unit Apartment, 1497 Martin St.

Here is a list of issues that should be addressed related to the fire restoration. Once you have reviewed these the City will require a copy of the construction value quote for the project this should include any additional works requested by the owners. The City will finalize the requirements for the permit application once we have received the above information.

- Emergency lighting required in all common areas including exit stairs, laundry, locker rooms etc.
- 2. Garbage room restore ¾ hr. fire rating to ceiling
- 3. Remove all mid-hallway doors
- 4. New Fire Alarm system to current BC Building Code
- 5. Smoke detectors are required in all corridors, exit stair shafts, storage/service and janitors rooms.
- 6. Hard wired smoke alarms are required in all suites.
- 7. Replace all suite doors with rated 20 min doors and frames c/w self-closures
- 8. Bathtub surrounds require fire rating to be continuous on rated walls throughout building.
- 9. Range and bathroom ducting to be enclosed in fire rated shafts throughout.
- 10. Garbage shaft to be decommissioned and the shaft firestopped at each floor
- 11. Handrails in the exit stairs should be continuous.
- 12. Elevator upgrade required which includes additional life safety devices confirm these requirements with the BC Safety Authority.
- 13. Unauthorized suite on ground floor to be removed.
- 14. All kitchen range exhaust systems are required to be vented through a ducting system - not a charcoal filter recirculated into the suite.
- 15. Exterior guardrails are nonconforming and are being recommended to be upgraded.

Yours truly,

Richard Wilson, RBO Planning and Development Services Direct Tel: 604.541.2136 Email: rwilson@whiterockcity.ca

lanning and Development Services P: 604.541.2136 | F: 604.541.2153

WHITE ROCK
My City by the Seal www.whiterockcity.ca

FIRE / RESCUE

15315 Pacific Avenue, White Rock, B.C. V4B 1R1 Phone: 604-541-2121 • Fax: 604-541-2120

INSPECTION REPORT

NAME: W	Westone - Mau) V	SHEET No.:	
ADDRESS: 🔠	497 Martin	St.	DATE:	.30,2011
TYPE OF INSPE	ection: Plan	Review		
AREA OF INSPE	ECTION:			
1. 5	mote 4 Heat	defectors.	should be	tupical
1+	all suite	is most in	et Tito	205 d 205
2 4	eat detector	required	1. in Lana	dry room
Le	ocker room.	on first f	llost,	1.5
3. 5	make defect	tor require	ed in cor	vidor to
la	undry and e	levaled roo	n.	
4. E	vergency 1/2	Lary requi	red in L	andry and
La	cker rooms.	, ,	^	1
5. F	Plan does a 2nd floor	of show	fire separ	ation door
11	2nd floor	Corridor.		
				/
6.	smoke deter	exter covere	age hallh	rays/
	staits.			
			\bigcap	<i>f</i> /
•		INSPECTO	18: B26 Se	hlase



WHITE STONE MANOR 1497 Martin Street, White Rock, BC

SCOPE OF WORK FOR REPAIR REQUIRED AFTER FIRE/WATER DAMAGE

This information is to be read in conjunction with accompanying notated building floor plans.

Main Floor-

- Install new gypsum board on corridor and stair walls and ceilings to locations shown on plans.
- Install 5/8" type gyp bd between studs / firestop where existing tub is on a fire separation.
- replace all suite entry doors with 20 minute rated solid core wood doors with peep hole, threshold and self closure. Reuse existing door hardware.

See attached for construction assemblies.

Second Floor-

- Install new gypsum board on corridor and stair walls and ceilings to locations shown on plans.
- Install 5/8" type gyp bd between studs / firestop where existing tub is on a fire separation.
- replace all suite entry doors with 20 minute rated solid core wood doors with peep hole, threshold and self closure. Reuse existing door hardware.

See attached for construction assemblies.

Unit 205:

- install new gypsum board to all walls/ceilings, see attached for construction assemblies
- replace existing exterior window and sliding glass door with new vinyl framed double glazed units c/w screens.
- install new kitchen and washroom cabinetry to building standard.
- install new interior doors/frames/hardware to building standard.
- install new building finishes to building standards.
- install 2 layers 5/8" type x gyp bd on ceilings.
- firestop all new/existing penetrations to walls/floors in fire separations.
- install new electrical /mechanical services to building standards.
- install new kitchen/ washroom exhaust ducts to the exterior wall and install drip cap and bug screens. See construction details.



Third Floor-

- Install new gypsum board on corridor and stair walls and ceilings to locations shown on plans.
- Install 5/8" type gyp bd between studs / firestop where existing tub is on a fire separation.
- replace all suite entry doors with 20 minute rated solid core wood doors with peep hole, threshold and self closure.. Reuse existing door hardware.

See attached for construction assemblies.

Unit 305:

- install new gypsum board to all walls/ceilings, see attached for construction assemblies
- install new kitchen and washroom cabinetry to building standard.
- install new interior doors/frames/hardware to building standard.
- install new building finishes to building standards.
- install 1/2" gyp bd on ceilings.
- firestop all new/existing penetrations to walls/floors in fire separations.
- install new electrical /mechanical services to building standards.
- install new kitchen/washroom exhaust ducts to the exterior wall and install drip cap and bug screens. See construction details.

Construction Assemblies

Wall type 1- 5/8" type x gyp bd/paint R12 batt insulation existing 2x4 stud wall existing 1/2" gyp bd.

Wall type 2- 5/8" type x gyp bd/paint existing solid wood framing

Wall type 3- 1/2" type x gyp bd/paint, both sides R12 batt insulation existing stud wall

Wall type 4- 1/2" gyp board /paint both sides existing stud wall


Wall type 5- 1/2" gyp bd/paint R14 batt insulation/6 mil vb existing stud wall/sheathing/stucco

Scott Gordon Architect


3370 WEST 44TH AVE VANCOUVER, B.C. V6N 3K8


TEL: 604.263.0410 FAX: 604.263.4106

- Ceiling type 1- 2 layers 5/8" type x gb/texture finish R12 batt insulation resilient channels @ 16" oc existing structure
- Ceiling type 2- 1/2" gyp bd /texture finish R28 batt insulation/6 mil vb existing structure





GROUND FLOOR KEY PLAN





THIRD FLOOR KEY PLAN






Redacted


CITHS APEX

ENTRI


SACHE FLOOR SEY BLA




(I) DESCORD PLOOP KEY PLAN



GENEWA - SEITTE X COE



been who



THEO FLOOR

5

SPECIALIZED PROPERTY EVALUATION CONTROL SERVICES LIMITED ETHICS ~ EXCELLENCE ~ VALUE ~ TEAMWORK

CONSTRUCTION BID DOCUMENT

FOR

File Name:

0819767 BC Ltd.

Location of Loss: O/A White Stone Manor

White Rock, B.C.

Adjuster:

Brent Serediak

ClaimsPro Inc.

Phone:

(604) 519-6067

Email:

brent.serediak@scm.ca

File #

53210-9991

SPECS File #:

10-36459

Issued for Tender November 10, 2011

BIDS TO BE RECEIVED IN THE SPECS OFFICES AT THE BELOW NOTED **ADDRESS** NO LATER THAN

2:00 PM November 29th 2011



Table of Contents

Contents

Table of Contents	
Invitation To Tender	
General Requirements	
Professionals	
Bid Submission	
Supplemental Costs Document	33



Invitation To Tender

You are hereby invited to submit a Tender for the:

Fire Damage Repairs

at

O/A White Stone Manor White Rock, B.C. V4B 3W8

- (1) The intent of the bid is to establish a fixed price for the work as per the general requirements, specifications and scope of work attached to this document.
- (2) Tender documents have been sent out from SPECS Limited on: November 3rd 2011 at 10 am.
- (3) Site access and conditions

 Lock Box at rear of building on gas meter code is "DFV"

 Alarm panel at end of hallway code is 5099
- (4) Contact person for inquiries is Aaron Visser:

Email:

avisser@specs.ca

Fax:

(604) 882-8940

Phone:

(604) 882-8930

Address:

20085 - 96 Avenue

Langley, BC V1M 3C6

(5) Tenders will be accepted via email, fax, courier, or hand no later than: 2:00 pm Friday November 29th ,2011

at

Email:

avisser@specs.ca

Fax:

(604) 882-8940

Phone:

(604) 882-8930

Address:

20085 - 96 Avenue

Langley, BC V1M 3C6

- (6) All tenders must be received in the format provided in this Bid Submission Form, including additional addenda. Incomplete submission forms will be considered not valid and may be rejected.
- (7) Any additional work required, but not identified within the attached Bid Documents, must be clearly identified and priced on the provided Supplemental Cost document. The Supplemental Cost document must be submitted with the Bid Submission form.



General Requirements

- 1. Please direct questions, discrepancies, noted errors, omissions or concerns to Aaron Visser at avisser@specs.ca
- 2. The notes and job scope are to be read in conjunction with the Architectural and Electrical drawings and notes, if a conflict is present whatever work is more onerous is to be priced and installed.
- 3. Perform the work in accordance with the latest edition of The National Building Code of Canada, including code supplements, safety codes, workers compensation legislation, local bylaws and all applicable governing legislation.
- 4. The General Contractor shall be responsible for the obtaining and payment of any and all necessary licenses, fees, permits, inspections etc. that are required to perform the work in the locale in which it is situated.
- 5. All materials and workmanship shall be of like kind and quality as existed prior to the loss in the structure and shall be in accordance with the trade standard manuals denoting workmanship, for that particular trade.
- 6. The General Contractor shall be responsible for the complete work in these documents including those items dictated by good practice in the details of all materials and methods even if they are not minutely detailed.
- 7. The contractor will be responsible to confirm all measurements and quantities by their own measurement.
- 8. Any contract awarded to the successful bidder will be between the contractor and the property owner and may be subject to the CCDC 2 contract form.
- 9. The bid will include, for reference, a proposed start and completion date. This information will be used in the decision making process.
- 10. The lowest or any tender may not necessarily be chosen.
- 11. The General Contractor will obtain and hold in force until the completion of this job a minimum of \$2,000,000 Contractor's General Liability insurance and a current account with The Workers Compensation Board plus whatever other insurance's are deemed necessary by the contractor.
- 12. The General Contractor shall provide a qualified job superintendent to be on site (or available by phone) at all times that work is being done under this scope of work.
- 13. The General Contractor shall be responsible to maintain the work site in a neat and orderly fashion to allow for safe entrance to the site and completion of the work.
- 14. The site shall be maintained free of waste and debris and to a broom clean condition on a daily basis.
- 15. The construction site is deemed to be a non-smoking site. The General Contractor shall be responsible for the enforcement of this requirement. Violation of this requirement shall result in the immediate and permanent dismissal of the offending person from the site.
- 16. The General Contractor shall be responsible for the final clean up of the site in preparation for an interim or final inspection.
- 17. The General Contractor shall be responsible for the reparation of any damages caused by, or as a result of, the repair work being carried out under this bid document.
- 18. The Contractor shall provide a one full year warranty on materials and workmanship for all work provided under this bid document. This warranty to be dated from the signing of the completion certificate by the owner.



Ethics - Excellence - Value - Teamwork

- 19. Progress invoices will be accepted on a monthly basis. Invoices sent are subject to a 10% hold back for 55 days beyond substantial completion of the work.
- 20. The HST on commercial projects must be collected from the owner of the property and should not be included in the commercial bid price.
- 21. The bids will be submitted on the attached form and will be valid for a period of 60 days.

-End of General Requirements-



TYPICAL FINISHES

For the purpose of this document the front of the building represents East.

Doors

Unit entry doors

- Metal slip on frame sealed and painted two (2) coats
- 3M foam weatherstripping
- Flat panel solid core stain grade door (20-min. fire rating) stained to finish
- 2" high unit numbers (brass)
- Brass peephole
- · Spartan deadbolt
- · Spartan nickel finish keyed entry passage set
- Brass hinges
- NOTE: Items needed for code upgrade are as follows:
 - o fire rated door without mail slot
 - o self-closing hinges or door closer

Bifold doors

- · Flat panel hollow core bifold door (flush finish)
- Decorative brass pull
- · Woodwork sealed and painted two (2) coats

Interior unit doors

- · Flat panel hollow core stain grade slab
- Brass hinges
- · Metal slip on frame sealed and painted two (2) coats
- Door stained to finish
- Standard grade brass passage set
- NOTE: Privacy passage set on bathroom door.

Corridor doors

- Flat panel solid core stain grade door (45 min. fire rating) stained to finish
- · Metal slip on door frames
- · Brass hinges and passage set
- · Taymor self closer

Ceilings

- Drywall with textured finish
- NOTE: Closets and bathrooms smooth finish.



Walls

Drywall sealed and painted two (2) coats as per architectural details and design

Flooring

- Oak face nailed, finished in place strip flooring to living room, dining room, hallway and bedrooms
- Sheet vinyl flooring in bathroom and kitchen (Armstrong Initiator)

Windows

- Single pane, aluminum frame code upgrade: double pane thermally broken vinyl frame
- 1x SPF window sill sealed and painted two (2) coats
- · Designview 2" faux wood blinds

Baseboard

Stain grade quarter round base to perimeter of all areas

Cabinetry

Upper and lower

- Built in place plywood boxes with flat panel doors and drawer fronts to be replaced with Builders grade flat panel thermafoil wrapped boxes, doors, and drawer fronts
 - o D-handle brass pulls
 - Surface mounted brass hinges
 - Flat laid laminate countertop with 4" backsplash
 - Total of approximately 12'6" of uppers
 - o Total of approximately 8'6" of lowers

ADDITIONAL ROOM FINISHES

Entry & Hallway

- Two (2) light fixture as per electrical specifications
- Closet rod and shelf to full width of entry closet
- Four (4) shelves to linen closet sealed and painted two (2) coats (each shelf measuring approximately 12" x 24")
- Intercom system (Mirtone)
- · Standard light switches and electrical outlets

Living Room

- Honeywell thermostat as per electrical details and design
- Standard light switches and electrical outlets as per electrical details and design
- . Hot water baseboard heat approximately 12 lineal ft.



No light fixture

Dining Room

- · One (1) light fixture as per electrical specifications
- Hot water baseboard heat approximately 5 lineal ft.

Kitchen

- One (1) light fixture as per electrical specifications
- Citadel 2-speed 24" range hood
- 24" 4-burner apartment size stove
- 24" apartment refrigerator
- · Single bowl stainless steel sink complete with 2-knob faucet
- 12" towel bar mounted to inside of cabinetry door under sink
- GE 12.1 cu. ft. Top Freezer No-Frost Refrigerator
- GE 24" Electric coil range

Bathroom

- Nutone bathroom fan
- Lighting and heat as per electrical details and design
- 24" chrome towel bar
- One (1) recessed medicine cabinet complete with mirrored door measuring approximately 16" x 26"
- 4' vanity consisting of:
 - o Recessed panel door fronts with D-handle pulls
 - o Surface mounted brass hinges
 - Raised panel drawer front
 - o Flat laid laminate countertop with 4" backsplash to all three (3) sides
- Crane toilet
- Enamel over steel bathtub complete with 3-knob chrome faucet, diverter valve and chrome spout
- · Chrome shower head
- Ceramic tile tub surround 2'3" down from ceiling height to tub (4' x 2'6", 4' x 5' and 4' x 2'6")
- Wall mounted chrome shower curtain rod
- Chrome toilet paper holder

Bedrooms

- One (1) light fixture as per electrical specifications
- One (1) keyless light fixture above closet entry door (inside)
- Hot water baseboard heater approximately 6 lineal ft.
- · Closet rod and shelf sealed and painted two (2) coats measuring 4 lineal ft.
- NOTE: Closet door is swing door as per bedroom entry door.



COMMON AREAS

Ceilings

Drywall textured finish, sealed and painted two (2) coats

Walls

- Drywall textured finish, sealed and painted two (2) coats
- 4' x 8' sheet paneling to lobby / entrance walls (North and South) offset @ 16" complete with full upright trims (refer to attached photo)
- · Wallpaper to North and South ends of corridors

Flooring

- Carpet and underpad to Hallways as per ICC validation # 745835
- Carpet and underpad to Stairwell as per ICC validation # 745836

Baseboard

- . 1" x 2" flat stock sealed and painted two (2) coats
 - End of Material and Finish Specifications-



SCOPE OF WORK

General Items

- All permitting costs are to be included in the bid
- Final Clean to all areas upon completion of work
- Provide new locks and keys complete with key schedule to building complete
- Smoke seal all exposed original sheathing and framing prior to installation of finishes.
- Fire stop all suite to corridor and suite to suite demising walls prior to application of fixtures or framing (ie: bathtub, framed drop)
- Pressure wash building exterior upon completion of repairs
- · Clean grounds upon completion of repairs
- Submit schedule of repairs detail with bid submission
- · Design, supply and install a fire safety plan for the entire building
- Supply and install signage, documentation and equipment in accordance with the fire safety plan including new fire extinguishers to all areas.
- Supply and install Aluminum wall mounted mail boxes for 20 unit capacity
- Supply and install new refrigerator and stove as per typical finishes to units 205 and 305
- Remove and replace refrigerator to all units
- · Remove and replace window coverings to all units as per typical finishes
- · Elevator repairs will be handled outside of this scope of work
- NOTE: ceiling texture has tested positive for asbestos, any painting of ceilings that have never been previously painted are to be done so under moderate risk Work Safe BC Regulations.

Electrical

- Remove and replace electrical wiring and devices to units 205 and 305 as well as common corridors as per attached electrical details and design
- Supply and install Fire Alarm System and emergency lighting as per attached electrical details and design (Code Upgrade Item)
- Complete all other electrical work detailed on attached electrical details and design
- Design, supply and install a metal cage to protect the electrical feed LB boxes on the
 exterior of the building (SE corner) Note: LB's must remain serviceable by way of tamper
 resistant mounting hardware to the cage
- Fire stop all exposed mechanical and electrical penetrations with approved fire stopping agents
- Test all exposed low voltage heating wiring prior to installation of finishes, replace any damaged wiring with new
- NOTE: New feed lines to units 205 and 305 are not required as per Megger testing completed by Wespac Electric. (Attached to this Scope of Work)

Mechanical

- Replace domestic water piping in units 205 and 305 with new in accordance with latest building code
- Supply and install new domestic water supply, waste and vent lines to exposed areas (unit 101 bathroom, 102 bathroom, 103 kitchen, 204 kitchen, 206 bathroom, 207 bathroom, 208 kitchen, 304 kitchen, 306 bathroom, 307 bathroom, 308 kitchen)



- Flush and rod both the storm drainage and the sanitary systems to remove all debris in entire system
- Pressure test water piping to building code specifications. Alternate tests as called for by plumbing inspector
- Test sanitary and storm to building code specifications, alternate tests as called for by plumbing inspector
- General service to boiler system including bleeding of zones and restoring hot water heat to all areas
- Remove and replace hot water heat registers to units 205 and 305 and common areas
- Fire stop all exposed mechanical and electrical penetrations with approved fire stopping agents
- · Fire stop all exposed mechanical chases as per architectural details and design



THIRD FLOOR

UNIT 301

- Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical
- NOTE: Temporary power for ongoing emergency work is wired into fuse panel.
- · Remove and disconnect temporary power

UNIT 302

- · Seal and paint walls and ceilings to unit complete
- · Seal and paint doors and trim work to unit complete (including shelving)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical

UNIT 303

- · Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical

UNIT 304

- Remove and replace oak hardwood flooring as per typical to living room, dining room, hallway, entry way and bedroom
- Detach and reset baseboard to areas where flooring replaced
- Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Seal and paint cabinetry to unit complete (inside and outside)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical

UNIT 305

- NOTE: Provide allowance for removal and replacement of ten (10) studs to account for warped / twisted studs and back framing.
- Supply and install plumbing vent stacks, plumbing supply and waste lines to unit complete
- Remove and replace electrical wiring and devices to suite complete. As per electrical details and design

Bedroom

 Supply and install insulation and 6 mil vapour barrier to exterior walls complete with sealed seams as per architectural details and design



- Supply and install batt insulation to suite to suite demising walls as per architectural details and design (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Supply and install insulation and 6-mil vapour barrier to ceiling complete with sealed seams as per architectural details and design
- Supply and install drywall to walls and ceilings as per architectural details and design
- Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- Seal and texture ceiling
- Supply and install baseboard heat to exterior wall approximately 6 lineal ft.
- Remove and replace oak hardwood flooring as per typical
- Supply and install baseboard as per typical
- Remove and replace 1x window sill
- Seal and paint window sill
- Supply and install window curtains and hardware
- Supply and install closet bypass door as per typical
- Supply and install closet shelving and closet rod (one shelf and rod East-West, one shelf and rod North – South)
- · Supply and install bedroom entry door as per typical

Bathroom

- Supply and install insulation and 6mil vapour barrier to ceiling complete with sealed seams as per architectural details and design
- Supply and install batt insulation to suite to suite demising walls (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- · Supply and install batt insulation to suite to hallway demising wall
- · Remove and replace bathroom exhaust fan complete with new venting
 - Upgrade venting to be routed to run north through entry way, kitchen and to the north suite to suite demising wall, then run East to exit East exterior wall
- · Remove and dispose of recessed heat lamp /light fixture
- Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- Seal and paint walls and ceiling two (2) coats
- Supply and install one (1) 6-bulb chrome bar style light fixture
- Supply and install recessed medicine cabinet sized to fit opening complete with mirrored door
- Supply and install vanity sized to fit opening as per typical
- Remove and replace linoleum to floor as per typical
- NOTE: At least two (2) layers for removal.
- Supply and install baseboard as per typical
- · Remove and replace sub floor system
- Remove and replace enamel over steel bathtub
- Remove and replace chrome spout
- · Remove and replace chrome diverter valve
- · Remove and replace chrome knob style hot and cold faucets
- Supply and install new chrome shower head
- Remove and replace Cranada toilet



- Supply and install Crane bathroom sink complete with self sealing rim and chrome faucet
- Supply and install bathroom entry door as per typical
- · Supply and install chrome toilet paper holder
- Supply and install ceramic tile tub surround as per typical
- · Supply and install chrome towel bar

Entry way

- Supply and install insulation and 6mil vapour barrier to ceiling complete with sealed seams as per architectural details and design
- Supply and install batt insulation to suite to hallway demising wall as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- Seal and texture ceiling
- Supply and install closet bifold door to entry closet as per typical
- · Supply and install closet rod and shelf to width of entry closet
- Seal and paint closet shelf
- Supply and install four (4) linen shelves to linen closet
- Seal and paint shelves
- Supply and install bifold door to linen closet as per typical
- Seal and paint bifold doors to entry and linen closets
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical
- Supply and install two (2) flush mount style light fixtures
- Remove and replace hardwood flooring as per typical
- · Supply and install baseboard as per typical

Kitchen

- Supply and install insulation and 6mil vapour barrier to celling complete with sealed seams as per architectural details and design
- Supply and install batt insulation to suite to hallway demising wall as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- Seal and texture ceiling
- · Supply and install one (1) globe style light fixture
- Supply and install upper and lower cabinetry as per typical
- Supply and install kitchen sink and faucet as per typical
- · Remove and replace linoleum to floor
- · Remove and replace sub floor system
- Remove and replace one (1) single speed 24" range hood fan complete with light
- Remove and replace ducting for hood fan



- NOTE: New ducting to run to north suite to suite demising wall. New drop to be framed
 in on north suite to suite demising wall to accommodate replacement of bathroom and
 kitchen venting.
- · Supply and install baseboard as per typical

Dining room

- Frame drop to north suite to suite demising wall to entire length of wall to accommodate new venting of kitchen and bathroom exhaust fans
- Supply and install insulation and vapour barrier to ceiling as per architectural details and design
- Supply and install batt insulation to suite to suite demising walls as per architectural details and design
- Supply and install batt insulation to suite to hallway demising wall as per architectural details and design (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Remove and replace temporary roof drain line with cast iron
- · Remove and replace face nailed oak strip flooring as per typical
- Supply and install baseboard as per typical
- Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- · Seal and paint walls two (2) coats
- Seal and texture ceiling
- · Remove and replace one (1) dish style light fixture
- · Supply and install hot water baseboard heater

Living room

- Supply and install insulation and 6mil vapour barrier to ceiling complete with sealed seams as per architectural details and design
- Supply and install batt insulation and vapour barrier to exterior wall as per architectural details and design
- Supply and install batt insulation to suite to suite demising walls as per architectural details and design (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Remove and replace face nailed oak strip flooring as per typical
- Supply and install baseboard as per typical
- Supply and install drywall to walls and ceiling
- Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- · Seal and texture ceiling
- Supply and install 1x window sill as per typical
- Supply and install window curtains and hardware
- NOTE: Roof is leaking at patio door area. Roof leak is pre-existing as per staining and will need to be repaired before finishes are installed.

UNIT 306

- Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Seal and paint cabinetry to unit complete (inside and outside)



- Supply and install new supply and waste lines to bathroom (cut and removed from unit 305)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical
- Remove and replace hardwood flooring with oak tongue and groove hardwood flooring to entryway, hallway, living, dining and bedroom
- Detach and reset baseboard to facilitate flooring replacement
- Refinish baseboard

UNIT 307

- Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Seal and paint cabinetry to unit complete (inside and outside)
- Supply and install plumbing supply and waste lines to bathroom
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical
- Remove and replace hardwood flooring with oak tongue and groove hardwood flooring to entryway, hallway, living and dining rooms
- Detach and reset baseboard to facilitate flooring replacement
- Refinish baseboard

UNIT 308

- · Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Seal and paint cabinetry to unit complete (inside and outside)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical
- NOTE: Roof is leaking in this unit at entry way section. Repairs not part of this scope of work



THIRD FLOOR COMMON CORRIDOR

South corridor

- Supply and install insulation and 6mil vapour barrier to ceiling complete with sealed seams as per architectural details and design
- Supply and install insulation to suite to corridor demising walls as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- Texture walls and ceilings
- · Seal and paint walls and ceilings two (2) coats
- · Supply and install carpet and underpad as per typical finishes
- · Supply and install baseboard to perimeter of area

South stairwell

- Supply and install insulation and vapour barrier to ceiling as per architectural details and design
- Supply and install insulation to suite to stairwell demising walls
- · Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- Texture walls and ceilings
- · Seal and paint walls and ceilings two (2) coats
- Remove and replace broken 1x trim board on East wall at stair riser
- Seal and paint trim board two (2) coats
- Supply and install carpet and underpad as per typical finishes
- Supply and install baseboard to perimeter of area as per typical
- Supply and install plumbing supply and waste lines to unit 308 kitchen area
- Supply and install tactile warning strips
- · Remove and replace corridor to stairwell door as per typical

North corridor

- Supply and install insulation and 6mil vapour barrier to ceiling complete with sealed seams as per architectural details and design
- Supply and install insulation to suite to corridor demising walls as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- Texture walls and ceilings
- · Seal and paint walls and ceilings two (2) coats
- Remove and replace garbage chute entry door slab and frame (to be 45 min fire rated) as per typical
- Seal and paint garbage chute area two (2) coats
- · Supply and install carpet and underpad as per typical finishes
- · Supply and install baseboard to perimeter of area as per typical



 Remove and replace 45 minute fire rated corridor to corridor and corridor to stairwell door and frame as per typical

North Stairwell to main floor

- · Seal and paint walls and ceilings complete (all floors)
- · Remove and replace carpet and underpad as per typical finishes
- · Seal and paint baseboard and trims



SECOND FLOOR

UNIT 201

- · No fire related damages noted at time of inspection.
- · Remove and replace entry door slab with 20-min. fire rated door slab

UNIT 202

- No fire related damages noted at time of inspection.
- Remove and replace entry door slab with 20-min. fire rated door slab

UNIT 203

- No fire related damages noted at time of inspection.
- · Remove and replace entry door slab with 20-min, fire rated door slab

UNIT 204

- Remove and replace oak hardwood flooring as per typical to living room, dining room, hallway, and entryway
- · Detach and reset baseboard to areas where flooring replaced
- · Supply and install vinyl flooring to kitchen room including subfloor
- Supply and install insulation to dining room ceiling as per architectural details and design
- Supply and install drywall to dining room ceiling as pre architectural details and design
- Tape and finish drywall repairs ready for paint
- · Texture dining room ceiling blending into existing
- Seal and paint walls and ceilings to unit complete
- · Seal and paint doors and trim work to unit complete (including shelving)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical
- Remove and replace bedroom flooring as per typical finishes
- Remove and replace water damaged drywall to NE corner of room (approximately 2'x6' section)
- Supply and install plumbing supply and waste lines to kitchen

UNIT 205 (source unit)

- NOTE: Account for removal and replacement of ten (10) studs to account for warped, twisted studs and back framing.
- Remove and replace electrical complete to this unit as per electrical details and design
- · Remove and replace original plumbing supply and waste lines complete to this unit

Bedroom

- Remove and replace aluminum framed bedroom window as per typical
- Remove and replace charred 2x4 framing members to bedroom entry door area
- Supply and install drywall to walls and ceiling as per architectural details and design



- Supply and install batt insulation and 6 mil vapour barrier to exterior walls as per architectural details and design
- Supply and install batt insulation to suite to suite demising wall as per architectural details and design (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Supply and install insulation to ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- · Seal and texture ceiling
- Remove and replace flush mount button style light fixture to ceiling
- Supply and install baseboard heat to exterior wall approximately 6 lineal ft.
- Remove and replace oak hardwood face nailed strip flooring
- Supply and install closet door as per typical
- Supply and install closet shelving and closet rod (one shelf and rod East-West, one shelf and rod North – South)
- Seal and paint closet shelving
- Supply and install 1x window sill
- Seal and paint window sill two (2) coats
- · Supply and install window curtains and hardware

Bathroom

- Remove and replace one (1) 2x3 drop ceiling
- · Remove and replace charred 2x4 to bathroom entry door area
- Supply and install insulation to ceiling complete with sealed seams as per architectural details and design
- Supply and install batt insulation to suite to suite demising walls (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Supply and install batt insulation to suite to hallway demising wall
- Remove and replace bathroom exhaust fan complete with new venting
- Upgrade venting to be routed to run north through entry way, kitchen and to the north suite to suite demising wall, then run East to exit East exterior wall
- Remove and dispose of recessed heat lamp / light fixture
- Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- Seal and paint walls and ceiling two (2) coats
- Supply and install one (1) 6-bulb chrome bar style light fixture
- Supply and install recessed medicine cabinet sized to fit opening complete with mirrored door
- Supply and install vanity sized to fit opening as per typical
- Remove and replace linoleum to floor as per typical
- Supply and install baseboard as per typical
- Remove and replace sub floor system
- Remove and replace enamel over steel bathtub
- Remove and replace chrome spout
- Remove and replace chrome diverter valve
- Remove and replace chrome knob style hot and cold faucets
- Remove and replace bathtub
- Supply and install new chrome shower head



- Remove and replace Cranada toilet
- Supply and install Crane bathroom sink complete with self sealing rim and chrome faucet
- · Supply and install bathroom entry door as per typical
- Supply and install chrome toilet paper holder
- · Supply and install ceramic tile tub surround as per typical
- Supply and install chrome towel bar

Entry way

- Supply and install insulation to ceiling as per architectural details and design
- Supply and install batt insulation to suite to hallway demising wall as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- Seal and texture ceiling
- Supply and install closet bifold door to entry closet as per typical
- · Supply and install closet rod and shelf to length of entry closet
- Seal and paint closet shelf
- Supply and install four (4) linen shelves to linen closet
- · Seal and paint shelves
- Supply and install bifold doors to linenand entry closet as per typical
- Seal and paint bifold doors to entry and linen closets
- Remove and replace entry door with 20-min, fire rated door and metal frame as per typical
- Supply and install two (2) ceiling hugger style light fixtures
- Remove and replace hardwood flooring as per typical
- Supply and install baseboard as per typical

Kitchen

- Remove and replace approximately five (5) charred study from east kitchen wall
- Remove and replace bulkhead on east and west kitchen walls measuring approximately
 6 lineal ft. each
- Remove and replace drop ceiling system in kitchen and dining room areas
- Supply and install insulation to ceiling as per architectural details and design
- Supply and install batt insulation to suite to hallway demising wall as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- · Tape and finish drywall ready for paint
- · Seal and paint walls two (2) coats
- Seal and texture ceiling
- Supply and install one (1) globe style light fixture
- · Supply and install upper and lower cabinetry as per typical
- Supply and install kitchen sink and faucet as per typical
- Remove and replace linoleum to floor
- Remove and replace sub floor system
- Remove and replace one (1) single speed 24" range hood fan complete with light



- Remove and replace ducting for hood fan
- NOTE: New ducting to run to north suite to suite demising wall. New drop to be framed in on north suite to suite demising wall to accommodate replacement of bathroom and kitchen venting.
- · Supply and install baseboard as per typical

Dining room

- Frame drop to north suite to suite demising wall to entire length of wall to accommodate new venting of kitchen and bathroom exhaust fans
- Supply and install insulation to ceiling as per architectural details and design
- Supply and install batt insulation to suite to suite demising walls as per architectural details and design
- Supply and install batt insulation to suite to hallway demising wall as per architectural details and design (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Remove and replace face nailed oak strip flooring as per typical
- Supply and install baseboard as per typical
- Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- · Seal and texture ceiling
- · Remove and replace one (1) dish style light fixture
- · Supply and install hot water baseboard heater

Living room

- Remove and replace valance to exterior wall
- Supply and install insulation to ceiling as per architectural details and design
- Supply and install batt insulation and vapour barrier to exterior wall as per architectural details and design
- Supply and install batt insulation to suite to suite demising walls as per architectural details and design (note: 2x6 top and bottom plates with staggered 2x4 studs at 8" oc)
- Remove and replace face nailed oak strip flooring as per typical
- Supply and install baseboard as per typical
- · Supply and install drywall to walls and ceiling
- · Tape and finish drywall ready for paint
- Seal and paint walls two (2) coats
- · Seal and texture ceiling
- Supply and install 1x window sill as per typical
- · Remove and replace aluminum framed patio door sized to fit opening
- Supply and install window curtains and hardware

UNIT 206

- · Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Seal and paint cabinetry to unit complete (inside and outside)
- Remove and replace entry door with 20-min. fire rated door and metal frame as per typical



- Supply and install new supply and waste lines to bathroom (cut and removed from unit 205)
- Remove and replace hardwood flooring with oak tongue and groove hardwood flooring to entryway, hallway, living and dining rooms
- · Detach and reset baseboard to facilitate flooring replacement
- Refinish baseboard

UNIT 207

- · Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Seal and paint cabinetry to unit complete (inside and outside)
- · Supply and install new supply and waste lines to bathroom
- Remove and replace entry door with 20-min, fire rated door and metal frame as per typical
- Remove and replace hardwood flooring with oak tongue and groove hardwood flooring to entryway, hallway, living and dining rooms
- Detach and reset baseboard to facilitate flooring replacement
- Refinish baseboard

UNIT 208

- · Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- · Seal and paint cabinetry to unit complete (inside and outside)
- Remove and replace entry door with 20-min, fire rated door and metal frame as per typical
- NOTE: As a result of roof leaking in unit 308, there is water damage in this unit that is not part of this scope of repair.



SECOND FLOOR COMMON CORRIDOR

South corridor

- Supply and install insulation to ceiling as per architectural details and design
- Supply and install insulation to suite to corridor demising walls as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- · Texture walls and ceilings
- Seal and paint walls and ceilings two (2) coats
- Supply and install carpet and underpad as per typical finishes
- Supply and install baseboard to perimeter of area

South stairwell to main floor

- Supply and install insulation to ceiling as per architectural details and design
- Supply and install R12 insulation to suite to stairwell demising walls
- · Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- · Texture walls and ceilings
- Seal and paint walls and ceilings two (2) coats
- Remove and replace electrical wiring and devices to area complete as per electrical details and design
- Remove and replace broken 1x trim board on East wall at stair riser
- Seal and paint trim board two (2) coats
- Supply and install light fixture as per typical
- · Supply and install carpet and underpad as per typical finishes
- · Supply and install baseboard to perimeter of area as per typical
- Supply and install plumbing supply and waste lines to unit 308 kitchen area
- · Supply and install continuous handrails
- Supply and install tactile warning strips
- · Remove and replace corridor to stairwell door as per typical

North corridor

- Supply and install insulation to ceiling complete as per architectural details and design
- Supply and install R12 insulation to suite to corridor demising walls as per architectural details and design
- Supply and install drywall to walls and ceiling as per architectural details and design
- Tape and finish drywall ready for paint
- · Texture walls and ceilings
- Seal and paint walls and ceilings two (2) coats
- Supply and install three (3) flush mount button style light fixtures as per typical
- Remove and replace garbage chute entry door slab and frame (to be 45 min fire rated) as per typical
- Seal and paint garbage chute area two (2) coats



- · Supply and install carpet and underpad as per typical finishes
- Remove and replace electrical wiring and devices to area complete as per electrical details and design
- · Supply and install emergency exit sign
- · Supply and install baseboard to perimeter of area as per typical
- Remove and replace 45 minute fire rated corridor to corridor and corridor to stairwell door and frame as per typical



FIRST FLOOR

UNIT 104

- Remove and replace entry door slab with 20-min. fire rated door slab
- · No fire related damage noted at time of inspection

UNIT 103

- Remove and replace entry door slab with 20-min. fire rated door slab
- · No fire related damage noted at time of inspection
- . NOTE: All other work to this unit is to be priced under the second claim.

UNIT 102

- Remove and replace entry door slab with 20-min. fire rated door slab as per typical
- Remove and replace flooring to entire bedroom as per typical finishes
- · Repair cutout subfloor
- NOTE: Damages to flooring in southwest bedroom are pre-existing.
- Detach and reset bifold doors and bedroom entry door to facilitate replacement of flooring.
- Detach and reset baseboards to facilitate replacement of flooring
- Seal and paint baseboards upon reinstallation
- · Seal and paint walls and ceilings
- · No other fire related damages noted to unit at time of inspection

UNIT 101

- Remove and replace entry door slab with 20-min. fire rated door slab
- Repair drywall damages to bathroom where plumbing lines removed
- No fire related damage noted at time of inspection.

CORRIDOR TO LAUNDRY ROOM AREA

- Supply and install carpet and pad as per typical finishes
- · Supply and install baseboard as per typical finishes

FIRST FLOOR CORRIDOR AND ENTRY / LOBBY AREA

- Supply and install insulation and vapour barrier to exterior walls as per architectural details and design
- Supply and install insulation to ceiling as per architectural details and design
- Supply and install insulation to suite to suite and suite to corridor walls as per architectural details and design
- · Supply and install drywall to walls and ceilings as per architectural details and design
- · Tape and finish drywall ready for paint



- Texture walls and ceilings
- . Seal and paint walls and ceilings two (2) coats
- Supply and install wood paneling to entry / lobby area walls as per typical finishes
- Supply and install carpet and underpad as per typical finishes
- · Supply and install baseboard as per typical
- · Seal and paint baseboard two coats
- Remove and replace corridor door slabs and metal frames with 45 min. fire rated door slabs as per typical



EXTERIOR

East side of building

- Smoke seal all exposed original framing and sheathing prior to installation of new finishes
- Remove and replace aluminum siding to unit 305 and 205 from south most section of 305 and 205 running north to north most section of 305 and 205
- Remove and replace stucco to unit 205 and 305 including underside of 305 deck
- Remove and replace stucco soffit including bug screen to unit 303, 304, 305, and 306
- Seal and paint siding, stucco and soffit to match existing
- Remove and replace 1x12 fascia board to deck of 305
- Seal and paint fascia board two (2) coats
- Detach and reset guard rail to 205 and 305 to facilitate siding replacement
- Clean, deodorize and refinish guardrails
- Clean, deodorize, seal and paint 205 and 305 exterior decking with an approved exterior grade decking paint
- · Remove and replace wire channels/raceways to facilitate siding replacement
- NOTE: settling cracks on south elevation are not as a result of fire damage and are not considered in this scope of repair.

-End of Scope of Work-



REPAIR BID DOCUMENT

FOR

File Name: 0819767 BC Ltd.

Location of Loss: O/A White Stone Manor

White Rock, B.C.

Adjuster:

Brent Serediak

ClaimsPro Inc.

Phone:

(604) 519-6067

Email:

brent.serediak@scm.ca

File #

53210-9991

SPECS File #:

10-37906

Issued for Tender November 10, 2011

BIDS TO BE RECEIVED IN THE SPECS OFFICES AT THE BELOW NOTED **ADDRESS**

NO LATER THAN 2:00 PM November 29th 2011



Table of Contents

Contents

Table of Contents	
Invitation To Tender	
General Requirements	
Bid Submission	12
Supplemental Costs Document	15



Invitation To Tender

You are hereby invited to submit a Tender for the:

Fire Damage Repairs

at

O/A White Stone Manor White Rock, B.C. V4B 3W8

- (1) The intent of the bid is to establish a fixed price for the work as per the general requirements, specifications and scope of work attached to this document.
- (2) Tender documents have been sent out from SPECS Limited on: November 3rd 2011 at 10 am.
- (3) Site access and conditions
 Lock Box at rear of building on gas meter code is "DFV"
 Alarm panel at end of hallway code is 5099
- (4) Contact person for inquiries is Aaron Visser:

Email:

avisser@specs.ca

Fax:

(604) 882-8940

Phone:

(604) 882-8930

Address:

20085 - 96 Avenue

Langley, BC V1M 3C6

(5) Tenders will be accepted via email, fax, courier, or hand no later than: 2:00 pm Friday November 29th, 2011

at

Email:

avisser@specs.ca

Fax:

(604) 882-8940

Phone:

(604) 882-8930

Address:

20085 - 96 Avenue

Langley, BC V1M 3C6

- (6) All tenders must be received in the format provided in this Bid Submission Form, including additional addenda. Incomplete submission forms will be considered not valid and may be rejected.
- (7) Any additional work required, but not identified within the attached Bid Documents, must be clearly identified and priced on the provided Supplemental Cost document. The Supplemental Cost document must be submitted with the Bid Submission form.



General Requirements

- Please direct questions, discrepancies, noted errors, omissions or concerns to Aaron Visser at avisser@specs.ca
- The notes and job scope are to be read in conjunction with the Architectural and Electrical drawings and notes, if a conflict is present whatever work is more onerous is to be priced and installed.
- Perform the work in accordance with the latest edition of The National Building Code of Canada, including code supplements, safety codes, workers compensation legislation, local bylaws and all applicable governing legislation.
- The General Contractor shall be responsible for the obtaining and payment of any and all
 necessary licenses, fees, permits, inspections etc. that are required to perform the work in
 the locale in which it is situated.
- All materials and workmanship shall be of like kind and quality as existed prior to the loss in the structure and shall be in accordance with the trade standard manuals denoting workmanship, for that particular trade.
- The General Contractor shall be responsible for the complete work in these documents including those items dictated by good practice in the details of all materials and methods even if they are not minutely detailed.
- The contractor will be responsible to confirm all measurements and quantities by their own measurement.
- Any contract awarded to the successful bidder will be between the contractor and the property owner.
- 9. The bid will include, for reference, a proposed starf and completion date. This information will be used in the decision making process.
- 10. The lowest or any tender may not necessarily be chosen.
- 11. The General Contractor will obtain and hold in force until the completion of this job a minimum of \$2,000,000 Contractor's General Liability insurance and a current account with The Workers Compensation Board plus whatever other insurance's are deemed necessary by the contractor.
- 12. The General Contractor shall provide a qualified job superintendent to be on site (or available by phone) at all times that work is being done under this scope of work.
- 13. The General Contractor shall be responsible to maintain the work site in a neat and orderly fashion to allow for safe entrance to the site and completion of the work.
- 14. The site shall be maintained free of waste and debris and to a broom clean condition on a daily basis.
- 15. The construction site is deemed to be a non-smoking site. The General Contractor shall be responsible for the enforcement of this requirement. Violation of this requirement shall result in the immediate and permanent dismissal of the offending person from the site.
- 16. The General Contractor shall be responsible for the final clean up of the site in preparation for an interim or final inspection.
- 17. The General Contractor shall be responsible for the reparation of any damages caused by, or as a result of, the repair work being carried out under this bid document.
- 18. The Contractor shall provide a one full year warranty on materials and workmanship for all work provided under this bid document. This warranty to be dated from the signing of the completion certificate by the owner.



- Ethics Excellence Value Teamwork
 - Progress invoices will be accepted on a monthly basis. Invoices sent are subject to a 10% hold back for 55 days beyond substantial completion of the work.
 - 20. The HST on commercial projects must be collected from the owner of the property and should not be included in the commercial bid price.
 - 21. The bids will be submitted on the attached form and will be valid for a period of 60 days.

-End of General Requirements-



TYPICAL FINISHES

For the purpose of this document the front of the building represents East.

Doors

Unit entry doors

- . Metal slip on frame sealed and painted two (2) coats
- 3M foam weatherstripping
- · Flat panel solid core stain grade door (20-min, fire rating) stained to finish
- 2" high unit numbers (brass)
- Brass peephole
- Spartan deadbolt
- Spartan nickel finish keyed entry passage set
- Brass hinges
- NOTE: Items needed for code upgrade are as follows:
 - o fire rated door without mail slot
 - o self-closing hinges or door closer

Bifold doors

- · Flat panel hollow core bifold door (flush finish)
- · Decorative brass pull
- Woodwork sealed and painted two (2) coats

Interior unit doors

- · Flat panel hollow core stain grade slab
- Brass hinges
- Metal slip on frame sealed and painted two (2) coats
- Door stained to finish
- Standard grade brass passage set
- NOTE: Privacy passage set on bathroom door.

Corridor doors

- Flat panel solid core stain grade door (45 min. fire rating) stained to finish
- Metal slip on door frames
- Brass hinges and passage set
- · Taymor self closer

Ceilings

- Drywall with textured finish
- NOTE: Closets and bathrooms smooth finish.



Walls

Drywall sealed and painted two (2) coats as per architectural details and design

Flooring

- Oak face nailed, finished in place strip flooring to living room, dining room, hallway and bedrooms
- Sheet vinyl flooring in bathroom and kitchen (Armstrong Initiator)

Windows

- Single pane, aluminum frame code upgrade: double pane thermally broken vinyl frame
- . 1x SPF window sill sealed and painted two (2) coats
- Designview 2" faux wood blinds

Baseboard

Stain grade quarter round base to perimeter of all areas

Cabinetry

Upper and lower

- Built in place plywood boxes with flat panel doors and drawer fronts to be replaced with Builders grade flat panel thermafoil wrapped boxes, doors, and drawer fronts
 - o D-handle brass pulls
 - Surface mounted brass hinges
 - Flat laid laminate countertop with 4" backsplash
 - Total of approximately 12'6" of uppers
 - o Total of approximately 8'6" of lowers

ADDITIONAL ROOM FINISHES

Entry & Hallway

- Two (2) light fixture as per electrical specifications
- Closet rod and shelf to full width of entry closet
- Four (4) shelves to linen closet sealed and painted two (2) coats (each shelf measuring approximately 12" x 24")
- Intercom system (Mirtone)
- Standard light switches and electrical outlets

Living Room

- Honeywell thermostat as per electrical details and design
- · Standard light switches and electrical outlets as per electrical details and design
- Hot water baseboard heat approximately 12 lineal ft.



No light fixture

Dining Room

- · One (1) light fixture as per electrical specifications
- Hot water baseboard heat approximately 5 lineal ft.

Kitchen

- · One (1) light fixture as per electrical specifications
- Citadel 2-speed 24" range hood
- 24" 4-burner apartment size stove
- · 24" apartment refrigerator
- · Single bowl stainless steel sink complete with 2-knob faucet
- · 12" towel bar mounted to inside of cabinetry door under sink
- GE 12.1 cu. ft. Top Freezer No-Frost Refrigerator
- GE 24" Electric coil range

Bathroom

- Nutone bathroom fan
- · Lighting and heat as per electrical details and design
- 24" chrome towel bar
- One (1) recessed medicine cabinet complete with mirrored door measuring approximately 16" x 26"
- 4' vanity consisting of:
 - Recessed panel door fronts with D-handle pulls
 - o Surface mounted brass hinges
 - o Raised panel drawer front
 - o Flat laid laminate countertop with 4" backsplash to all three (3) sides
- Crane toilet
- Enamel over steel bathtub complete with 3-knob chrome faucet, diverter valve and chrome spout
- Chrome shower head
- Ceramic tile tub surround 2'3" down from ceiling height to tub (4' x 2'6", 4' x 5' and 4' x 2'6")
- Wall mounted chrome shower curtain rod
- · Chrome toilet paper holder

Bedrooms

- One (1) light fixture as per electrical specifications
- One (1) keyless light fixture above closet entry door (inside)
- Hot water baseboard heater approximately 6 lineal ft.
- · Closet rod and shelf sealed and painted two (2) coats measuring 4 lineal ft.
- NOTE: Closet door is swing door as per bedroom entry door.



COMMON AREAS

Ceilings

Drywall textured finish, sealed and painted two (2) coats

Walls

- Drywall textured finish, sealed and painted two (2) coats
- 4' x 8' sheet paneling to lobby / entrance walls (North and South) offset @ 16" complete with full upright trims (refer to attached photo)
- · Wallpaper to North and South ends of corridors

Flooring

- Carpet and underpad to Hallways as per ICC validation # 745835
- Carpet and underpad to Stairwell as per ICC validation # 745836

Baseboard

- 1" x 2" flat stock sealed and painted two (2) coats
 - End of Material and Finish Specifications-



SCOPE OF WORK

General Items

- Final Clean to all areas upon completion of work
- NOTE: ceiling texture has tested positive for asbestos, any painting of ceilings that have never been previously painted are to be done so under moderate risk Work Safe BC Regulations.

UNIT 308

- Supply and install insulation to ceiling in entryway where removed
- · Supply and install drywall to ceiling in entryway where removed
- · Tape and finish drywall repairs ready for paint
- · Seal and texture drywall repairs blending into existing
- Remove and replace hardwood flooring as per typical finishes to entry, hallway, living, and dining rooms
- Detach and reset baseboard to facilitate repairs
- Refinish baseboards

UNIT 208


- · Supply and install insulation to ceiling in entryway where removed
- · Supply and install drywall to ceiling in entryway where removed
- · Tape and finish drywall repairs ready for paint
- Seal and texture drywall repairs blending into existing
- Remove and replace hardwood flooring as per typical finishes to entry, hallway, living, and dining rooms
- Detach and reset baseboard to facilitate repairs
- Refinish baseboards


UNIT 103


- Supply and install vinyl flooring to kitchen as per typical
- · Supply and install subfloor to kitchen
- Supply and install insulation to ceiling as per architectural details and design where cut
 out to dining to area measuring approximately 6'x6'
- Supply and install drywall to ceiling as per architectural details and design to area measuring approximately 6'x6'
- Tape and finish drywall ready for paint
- Texture ceiling blending into existing
- Remove and replace oak hardwood flooring as per typical to living room, dining room, hallway, entryway, and bedroom
- Detach, reset and refinish baseboard to areas where flooring replaced
- Seal and paint walls and ceilings to unit complete
- Seal and paint doors and trim work to unit complete (including shelving)
- Remove and replace entry door with 20-min, fire rated door and metal frame as per typical




-End of Scope of Work-









SUITE NOTES:

- 1 ALL BEDROOM RECF CIRCUIT BREAKER ALL BEDROOM RECEPTACLES TO BE ON ARC-FAULT
- CONNECT SMOKE ALARM TO UN-SWITCHED WIRING OF A 2 LIGHTING CIRCUIT IN SUITE PANEL. SMOKE ALARMS WITHIN A SUITE SHALL BE WIRED TOGETHER SO THAT THE ACTIVATION OF ONE ALARM WILL CAUSE ALL ALARMS TO SOUND
- FOR TELEPHONE AND INTERNET: 8"x8"x4" JUNCTION BOX C/W TO TELEPHONE AND INTERNET OF AN ATTEMPT OF THE AND INTERNET OF THE AND INSTALLED BY DIV. 16. FOR TERMINATION OF THE AND ETHERNET OUTLETS IN-SUITE WIRING OF TEL AND ETHERNET OUTLETS
- 4 HORIZONTAL SUITE STATION CONNECTED TO EXISTING MIRCOM IS-401B-WHITE c/w 1B-2A BACKBOX.
- ALL SUITE PANELS ARE TO BE RECESSED MOUNTED COMPLETE WITH HINGED DOOR AND TYPE WRITTEN PANEL DIRECTORIES
- RECEPTACLE 5-15R FOR FRIDGE. DEDICATED 15A-1P
- RECEPTACLE 5-15R FOR MICROWAVE, DEDICATED 15A-1P
- RECEPTACLE 20AMP 5-20R FOR COUNTER PLUG.
- NEW WALL MOUNTED TELEPHONE LINE TO CONNECT TO EXISTING ENTERPHONE
- 40AMP-240V-1¢ RECEPTACLE FOR RANGE. 3C#8 CABLE
- CONTRACTOR TO SUPPLY & INSTALL NEW 300 WATT 120VOLT 10 COMPACT KICK SPACE HEATER AT BATHROOM MILLWORK. COORDINATE WITH GENERAL CONTRACTOR TO CUT GWB , FISH WIRING INTO MILLWORK AND PATCH. KICK SPACE HEATER TO BE OUELLET OCP SERIES 300WATT 120VOLT 10 KICK SPACE HEATER C/W REMOTE THERMOSTAT. TYPICAL FOR UNIT 205 & 305.

GENERAL NOTES:

- PRIOR TO COMMENCING INSTALLATION, CONFIRM LAYOUT OF AREAS WITH LATEST ARCHITECTURAL DRAWINGS AND ADJUST TO
- CO-ORDINATE ALL KITCHEN OUTLET LOCATIONS AND HEIGHTS WITH THE ARCHITECTURAL ELEVATIONS.
- CONTRACTOR TO ENSURE MINIMUM CLEARANCES FOR ALL DEVICES IN WASHROOMS AS PER THE CANADIAN ELECTRICAL CODE.
- 4.) ALL RECEPTACLES OF CSA CONFIGURATION 5-15R AND 5-20R FOR RESIDENTIAL UNITS MUST BE TAMPER RESISTANT TYPE AND SHALL BE SO MARKED.

PANEL:S	LOCATION: UNITS (T	YPICAL)	PAINTED: GRAY						S
■120/240V 1ø/3W							■ DOOR	LOCK	16 CCT.
100	A MAIN BREAKER	GROUND	BAR:	■ NO	RMAL		INSTALLED: SURF	ACE	
SPEC. NOTE:	DESCRIPTION	CB	RCUIT	CCT	ССТ	CIRCUIT BREAKER	DESCRIPTION		SPEC. NOTE:
_	COUNTER PLUG		20A	1	2		RANGE		-
	COUNTER PLUG			3	4	40A	RANGE		-
-	FRIDGE			5	6	15A	RECEPTACLES		AR
-	MICROWAVE		15A	7	8	15A	RECEPTACLES		-
-	SPARE		15A	9	10	15A	LIGHTS		_
GFI	GFCI		15A	11	12	15A	LIGHTS		
_	SPARE		15A	13	14	154	0.405 B0.405 UE		
_	SPARE			15	16	15A BASE BOARD HEATER			_

PANEL NOTES:


- PROVIDE 100A-2P MAIN BREAKER AT PANELS 205 & 305.
- CONTRACTOR TO REMOVE AND REPLACE SUITE FEEDER TO 205 & 305. 3C#2 N.M.D LOOMEX.

ARC - ARC FAULT CIRCUIT BREAKER

	EME	RGENCY	BATTER	RY UNIT	SCHE	DULE
TAG	WATTS	CIRCUIT #	DC VOLT	MOUNTING HEIGHT	HEAD TYPE	NOTES
EB-1	75	NL	12	ABOVE DOOR	QUARTZ	GROUND FLOOR
EB-2	75	NL	12	ABOVE DOOR	QUARTZ	SECOND FLOOR
EB-3	75	NL	12	ABOVE DOOR	QUARTZ	THIRD FLOOR
EB-4	75	NL	12	+7'-6"	QUARTZ	SOUTH STAIR
EB-5	75	NL	12	+7'-6"	QUARTZ	NORTH STAIR
EB-6	36	NL	12	ABOVE DOOR	QUARTZ	ELEC./MACHINE ROOM

- 1) EMERGENCY LIGHT UNITS MUST BE FED FROM NORMAL LIGHTING
- CIRCUITS IN AREAS IN WHICH THEY SERVE. 2) CONTRACTOR TO WIRE ALL REMOTE HEADS TO BATTERY PACK INDICATED. SEE TABLE BELOW FOR WIRE SIZE. ALL WIRING TO
- BE RUN IN CONDUIT MINIMUM 1/2"- 2 #12 RW90. 3) ALL REMOTE HEADS TO BE EMERGI-LITE EF9DQ-12V-12W MINIATURE QUARTZ.
- 4) BATTERY PACKS TO BE EMERGI-LITE 12ESL SERIES

EN	MERGENCY LENGTH OF V						20000	=5		
	13W	18W	25W	30W	35W	50 W	60W	75W	100W	150W
#12 AW	G 165	110	85	71	61	42	35	29	22	14
#10 AW	G 260	190	136	112	97	68	52	45	34	23
#8 AW	G 415	300	215	180	154	108	90	72	54	36



TYPE	DESCRIPTION	VOLT	LAMPS	MOUNTING			
SA	TRI CLIP, ALABASTER DISH FIXTURE GALAXY 396501	120	2-60WATT A19	SURFACE			
SB	3 FOOT INCANDESCENT BATHBAR c/w 4 LAMPS 120 5x60W G WALL INCANDESCENT						
	COMMON AREA FIXTUI	RE SCHE	DULE				
A	TRI CLIP, ALABASTER DISH FIXTURE GALAXY 396501	120	1-100WATT A19	SURFACE			
В	DECORATIVE WALL SCONCE GALAXY 221217	120	1x60W A19	WALL			
EX	ECONOMY GRADE LED EXIT SIGN c/w TWO EMERGENCY HEADS WHERE APPLICABLE	12/	LED AND 2x9W QUARTZ	UNIVERSAL			

		MECHA	NICAL E	QUIPME	NT S	SCHEDU	JLE		
NO.	DESCRIPTION	LOCATION	LOAD	VOLTAGE	PH.	FEEDER	BREAKER	CIRCUIT	NOTE
EF-1	EXHAUST FAN	WASHROOM	FRAC.	120	1	2C#14	15A-1P	SUITE PANEL	4
RH	RANGE HOOD FAN	KITCHEN	2A	120	1	2C#14	15A-1P	SUITE PANEL	-
BB	BASEBOARD HEATER	VARIOUS	VARIOUS	240	1	2C#12	15A-2P	SUITE PANEL	5

- 1) ALL EQUIPMENT SUPPLIED AND INSTALLED BY DIV. 15 CONNECTED BY DIV. 16. 2) DIVISION 16 TO SUPPLY AND INSTALL AND CONNECT RAINTIGHT DISCONNECTS FOR ALL UNITS. SEE PLANS FOR LOCATION.
- 3) ALL 120V. OR GREATER WORK TO BE DONE BY DIV. 16.
- 4) CONTROLLED VIA LIGHT SWITCH BY DIVISION 16.
- ALL BASEBOARD HEATERS SUPPIED, INSTALLED & CONNECTED BY DIV. 16 OUELLET OFM SERIES 240V-1¢ WHITE c/w STAT.

SP	ECIFICATIONS:
16.1	GENERAL REQUIREMENTS

- THESE DRAWINGS HAVE BEEN DESIGNED FOR THE SOLE PURPOSE OF THIS BUILDING, AS A DESIGN BUILD SERVICE BY SML ELECTRICAL CONSULTANTS LTD. FOR SPECS. NO OTHER CONTRACTOR OR INSTALLER WILL BE PERMITTED OR RETAINED.
- CONFIRM THE LOCATION OF ALL MECHANICAL EQUIPMENT (AIR CONDITIONING UNITS, CEILING FANS, EXHAUST FANS AND HOT WATER TANKS WITH DIVISION 15 PRIOR TO ROUGH IN.) ALL OF THE ABOVE EQUIPMENT IS SUPPLIED AND INSTALLED BY DIVISION 15 CONNECTED BY DIVISION 16. CO-ORDINATE SPRINKLER EQUIPMENT CONNECTION WITH SPRINKLER CONTRACTOR.
- THE CENERAL CONTRACTOR IS TO MAINTAIN ALL ARCHITECTURAL FIRE RATINGS. THE ELECTRICAL CONTRACTOR IS TO ADVISE THE GENERAL CONTRACTOR OF THE ELECTRICAL PENETRATIONS AT FIRE RATED ASSEMBLIES. THE GENERAL CONTRACTOR IS TO SUPPLY AND INSTALL APPROVED FIRE STOPPING MATERIALS AS REQUIRED AROUND ALL ELECTRICAL PENETRATIONS.
- CONTRACTOR TO MAINTAIN ONE METER CLEARANCE IN ELECTRICAL ROOM.
- B) ALL EMERGENCY LIGHTING MUST BE FED FROM LIGHTING CIRCUIT IN AREA WHICH THEY SERVE. SEPERATE NIGHTLIGHT CIRCUIT. CONTRACTOR TO PAY FOR ALL PERMITS, FEES AND CERTIFICATES FOR THE ELECTRICAL INSTALLATION.

16.2 EMERGENCY LIGHTING

- t) PROVIDE EMERGENCY AND EXIT LIGHTING EGRESS SYSTEM AS REQUIRED BY THE B.C. BUILDING CODE. 2) ALL EMERGENCY HEADS TO BE 12 WATT QUARTZ.
- REFER TO THE EMERGENCY BATTERY UNIT SCHEDULE FOR UNIT SIZES AND WIRING REQUIREMENTS. 4) EMERGENCY PACKS TO BE RELAY CONTROLLED BY THE LIGHT CIRCUITS IN AREAS SERVED BY EMERGENCY PACK AND REMOTE HEADS.
- 5) THE EMERGENCY LIGHTING IS REQUIRED TO BE DESIGNED TO OPERATE AUTOMATICALLY UPON FAILURE OF THE REGULAR POWER SUPPLY FOR A PERIOD OF AT LEAST 30
- MINUTES. B.C.B.C. [3.2.7.4] 5) PROVIDE 24—HOUR LONG (10 YEAR) LIFE BATTERY BACK—UP.
- 7) SELF CONTAINED EMERGENCY LIGHT UNITS ARE REQUIRED TO CONFORM TO C22.2 #141 AND B.C.B.C. [3.2.7.4(2)]

16.3 FIRE ALARM SYSTEM

- INSTALLATION SUBJECT TO APPROVAL, INSPECTION AND TEST OF ENGINEER AND FIRE MARSHALL FOR FINAL ACCEPTANCE.
- ALL EQUIPMENT SHALL BE LISTED BY UNDERWRITERS LABORATORY OF CANADA. 3) SYSTEM TO BE PROVIDED IN ACCORDANCE WITH LATEST
- EDITION OF CAN/ ULC-S524.
- 4) ALL WIRING METHODS AND MATERIALS USED IN THE INSTALLATION OF THE FIRE ALARM SYSTEM SHALL CONFORM TO THE REQUIREMENTS FOR BRANCH CIRCUIT WIRING AS OUTLINED IN THE C.E.C. 5) THE VERIFICATION SHALL BE IN ACCORDANCE WITH LATEST
- EDITION OF CAN/ULC-S537. THE SYSTEM MANUFACTURER IS PRE-APPROVED TO PERFORM THE VERIFICATION. 6) THE FIRE ALARM SYSTEM IS TO BE MONITORED IN ACCORDANCE WITH NFPA-72, BC BUILDING CODE SECTION 3.2.4. AND CAN/ULC S561. PANEL TO BE C/W MONITORING CARD AND AUTO DIALER, ULC USTED FOR FIRE ALARM SIGNALS. CONNECT TWO TELEPHONE LINES FOR OFF SITE MONITORING. CONTRACTOR TO COORDINATE THE MONITORING CONNECTION WITH THE OWNER AND THE
- TELEPHONE COMPANY PRIOR TO OCCUPANCY. 7) THE FIRE ALARM SEQUENCE OF EVENTS IS AS FOLLOWS; -THE MAIN FIRE ALARM PANEL IS ZONED AND MONITORED.
- -UPON ACTIVATION OF A PULL STATION OR FIRE DETECTOR, ALL NOTIFICATION APPUANCES WILL BE ACTIVATED. -THE AUTO DIALER WILL ALERT A CERTIFIED OFF SITE MONITORING COMPANY, WHO WILL IN TURN NOTIFY THE FIRE DEPARTMENT.
- -THE FIRE ALARM ANNUNCIATOR WILL INDICATE THE ZONE WHICH HAS BEEN ACTIVATED. 8) AN EMERGENCY POWER SUPPLY IS REQUIRED FOR THE F/A SYSTEM THAT WILL PROVIDE SUPERVISORY POWER FOR 24 HOURS PLUS AN ADDITIONAL 30 MINUTES OF EMERGENCY POWER UNDER FULL LOAD. B.C.B.C. [3.2.7.8.]

ZONE	DESCRIPTION	NOTE
1	GROUND FLOOR DEVICES	
2	SECOND FLOOR DEVICES	
3	THIRD FLOOR DEVICES	
4	SOUTH STAIRWELL	SMOKE AT TOP OF STAIR
5	NORTH STAIRWELL	SMOKE AT TOP OF STAIR
6	ELEVATOR SHAFT	SMOKE AT TOP OF SHAFT
7	SPARE	
8	SPARE	
9	SPARE	
10	SPACE	
11	SPACE	
12	SPACE	
13	SPACE	
14	SPACE	
15	SPACE	
16	SPACE	

SYMBOL	DESCRIPTION	MOUNTING
	SINGLE POLE TOGGLE SWITCH 3-3 WAY MS-MOTOR STARTER	+48" A.F.F.
\$	D-DIMMER MR-MOTOR RATED LY-LOW VOLTAGE K-KEY	+48" A.F.F.
	S - SPEED SWITCH MIC-MICROWAVE S-PULLCHAIN	+48" A.F.F.
\$	TOGGLE SW - 2GANG # 3 GANG (ETC.)	+48" A.F.F.
DENOTES	GFT - GROUND FAULT INTERRUPTER IC - ISOLATED GROUND EX - EXISTING AFF ABOVE FINISHED FLOOR POWER WP - WEATHERPROOF DED DEDICATED NL - NIGHT LIGHT RT - RAIN TIGHT	
40	DISCONNECT	
45	FUSED DISCONNECT	
- 🛭	3 PHASE MAGNETIC MOTOR STARTER OR CONTROL PANEL	
0	EXHAUST FAN OR EQUIPMENT CONNECTION	
Ф	DUPLEX RECEPTACLE	+12" A.F.F.
Ф	20AMP-5-20R RECEPTACLE	AS NOTED
#	DOUBLE DUPLEX RECEPTACLE	AS NOTED
Ф	SPECIAL DUTLET - AS NOTED	AS NOTED
•	SWITCHED RECEPTACLE	AS NOTED
Ø	ISOLATED GROUND RECEPTACLE	AS NOTED
unn	BRANCH CIRCUIT PANELBOARD	6'-6" TO TOP
onn	RECESSED BRANCH CIRCUIT PANELBOARD	6'-6" TO TOP
0—	INDICATES HOME RUN TO DESIGNATED PANEL	*****
-#-	INDICATES NUMBER OF CONDUCTORS IN CONDUIT	WP-144
•	PUSH BUTTON	+54" A.F.F.
O/19	JUNCTION BOX OR EQUIPMENT CONNECTION	
•	TELEPHONE OUTLET	+12" A.F.F.
▽	DATA OUTLET	+12" A.F.F.
4	DATA & TELEPHONE OUTLET	+12" A.F.F.
•	CATY OUTLET	+12" A.F.F.
•	MAIN TELEPHONE ENTRY BOX	AS NOTED
	MAIN CATV ENTRY BOX	AS NOTED
ФФ	DUPLEX RECEPTACLE & TELEPHONE/DATA OUTLET COMBINATION FLOOR BOX	FLUSH WITH FLOOR
	THERMOSTAT	+54" A.F.F.
0.75	DENOTES AMOUNT OF BASEBOARD HEAT REQUIRED IN K.W.	
	2FT. x 4FT. FLUORESCENT FIXTURE c/w LOUVRE AS SPECIFIED	RECESSED
	2FT. x 4FT. FLUORESCENT FIXTURE c/w LENS AS SPECIFIED	RECESSED
NL NL	DENOTES FIXTURE TO BE WIRED TO NIGHT LIGHT CIRCUIT	AS NOTED
	1FT. x 4FT. FLUORESCENT FIXTURE c/w LENS AS SPECIFIED	AS NOTED
(A)	LUMINAIRE AS SPECIFIED	CEILING
0	WALL LUMINAIRE	WALL
	WALL PACK	WALL
D	WALL SCONCE	WALL
000	POLE MOUNTED LUMINAIRE	POLE
● _{120V}	12DVOLT SMOKE ALARM	CEILING
8	FIRE ALARM HEAT DETECTOR	CEILING
6	BUZZER	WALL AT HIGH LEVEL
<u> </u>	FIRE ALARM MANUAL PULL STATION	+54" A.F.F.
0	FIRE ALARM 10° GONG	+84" A.F.F.
FAP	FIRE ALARM PANEL	WALL
ENT	IN SUITE ENTERPHONE, SEE SPECS.	WALL

OCT 28, 2011	
NOV 2, 2011	ISSUED FOR BUILDING PERMIT/ CONSTRUCTION
-	
	- more and the second
,,,,,	- 10 × 1.00c.1000

REVISIONS

SML CONSULTANTS GROUP LTD.

PROFESSIONAL ELECTRICAL CONSULTING SERVICES #109 - 7225 BROWN STREET

DELTA, BC V4G 1G5 TEL: (604) 946-7680

EMAIL ADDRESS FAX: (604) 946-7682 inbox@smlconsultants.ca

FIRE RESTORATION OF 20 UNIT APARTMENT

CIVIC ADDRESS: 1497 MARTIN STREET WHITE ROCK B.C.



ELECTRICAL SUITE LAYOUT, SCHEDULES AND SPECIFICATIONS

DRAWING NO .: PROJECT NUMBER: SML - 1179 **E4** of 4 AS NOTED OCTOBER 2011



THE CORPORATION OF THE CITY OF WHITE ROCK

PLANNING AND DEVELOPMENT SERVICES
15322 Buena Vista Avenue, White Rock, B.C. V4B 1Y6

Inspection Report

City Hall, White Rock, B.C. Tel: 604-541-2136 Fax: 604-541-2153

N	AME: OWNCT PERMIT No
AI	DDRESS: 1497 Martin St. SHEET No
	PE OF INSPECTION: life safety . DATE: Aug . 17, 2011
AF	REA OF INSPECTION: building fire -
	Places to a room diest life ander
	Please be aware that a life safety
	uggrade will be required because of the
	age and extent of fire damage.
	This upgrade should include:
	· hardwired smore alarms to each unit ·
	· fire detectors installation in common
	oreos.
	· settelosures required on each shite door.
	c'an la do to BCBC
	- emergency lighting to be reviewed required.
	emergency lighting to be reviewed required.
	A builting permit is required for fire clamage regains.
CIONAT	words to he
	URE: INSPECTOR: FUND
DAIE: _	

Please sign this form when the work is completed and return to the above department.